

**Operating instructions  
Digital handheld  
pressure gauge**



**HM28**


## Contents

1	Description .....	4
2	Safety details .....	4
3	Operating .....	4
3.1	Switching on and off .....	4
3.2	Pneumatic connection .....	4
3.3	Operating modes .....	4
3.4	Configuration .....	6
3.5	RS 232 mode .....	7
3.6	Battery change .....	10
3.7	Recalibration .....	10
4	Specifications .....	10
4.1	Technical data .....	10
4.2	Measuring ranges .....	12
4.3	Mains supply unit connection .....	12
5	Maintenance .....	12
6	Warning messages and faults .....	13
7	Accessories .....	13
8	Calibration instructions .....	14

# Operating instructions

ON = On  
OFF = Off  
MODE = Select operating mode  
- Pressure measurement  
- Min./Max.  
- Leak rate  
- Datalogging  
CLEAR/ZERO = Zero setting  
PRINT/HOLD = Print and freeze display  
START/STOP = Data recording / printing  
SET = Select config. modes  
SELECT = Select config. data

- ① Matrix display
- ② Connection for pneumatic hoses
- ③ Connection for plug-in power supply unit
- ④ Connection for RS 232 interface



## Important!

**i** Please note warning symbol  
in the operating instructions.

Copyright (c) by LOVE CONTROLS.  
The contents of this publication may not be  
copied without the express permission of  
LOVE CONTROLS.  
Subject to dimension and design changes.

## 1 Description

The „LOVE CONTROLS“ handheld pressure gauge HM28 is a digital pressure measuring instrument with integrated pressure sensor for the measurement of differential, relative or absolute pressures and vacuum. Its versatile range of functions and high precision makes it suitable for a wide range of applications.

Configuration possibilities:

- Autom. switching off, selectable time
- Selectable resolution and damping
- Selectable units of time
- Selectable measurement units
- General reset to standard setting
- Selectable data transfer rate
- Configuration printout
- Selectable measuring intervals

## 2 Safety details

The pressure values stated on the rating plate and mentioned in these operating instructions must not be exceeded otherwise the pressure sensor can be destroyed.



**Do not use the instrument in danger zones (explosives zones)!**  
**Wear eye protection for pressures > 1bar!**

## 3 Operating

### 3.1 Switching on and off

**Switching on** Press the ON key (the maximum permissible measuring range and the class appears on the display).

For precision measurements the instrument must be switched on for at least 1 minute (warm-up phase).

**Switching off** Press the OFF key, or automatic switching off 1,10 or 60 min after the last keystroke.

In case of a temperature change the instrument requires at least 30 minutes to adjust to the new ambient temperature.

### 3.2 Pneumatic connection

For measuring ranges up to 7000 mbar, 4/6 mm or NPT 1/8" connectors can be connected depending on model. Higher ranges are equipped with NPT 1/8".

Ensure correct connection of the pneumatic hoses!

**+P** high pressure

**S-** low pressure (not available with the absolute and relative pressure version)

Measuring negative differential or relative pressures:

connect “**S-**” → negative pressure,  
or  
change ports “**S-**” and “**+P**”.

The HM28 will display a positive value.



**When screwing on a coupling it is important to hold with a spanner in the opposite direction. Never hold at case only!**

### 3.3 Operating modes

The modes in the matrix below can be selected in succession by pressing the MODE key.

After switching ON, the instrument is **always in the mode „normal“**.

	 MODE SET	 START/STOP SELECT	 PRINT HOLD	 CLEAR ZERO	Display example	Notes
Switching on					Max. Range: 200 mbar	
					Full scale error 0.05 %	
Normal (differential) and analogue/hold	print hold	zero display			123.45 mbar ===== or HLD 123.4 mbar	<b>Only with differential or relative pressure models</b> Hold, store indicated value
Normal (absolute) and differential	print	zero diff	DIF		1013.2 mbar 1013.2 mbar	<b>Only with absolute pressure mode</b> Zero sets Diff to 0
Zoom	print	zero display			123 . 45	Measurement in large figures
Min/Max	print	zero (reset)	MAX	150.0 mbar		With absolute pressure, reset to actual value
Leak rate	print	zero display	MIN	100.0 mbar		
Tendency (absolute)	print		LEK	1234.5 mbar 2.1 /min		<b>Only with Diff./Rel.</b> (unit/time unit)
Record 1)	start/stop	clear memory	REC	432.1 mbar		If measurement memory cleared
			STOP	30 s MEM 1		
			REC	432.1 mbar		Recording runs up to 964 values
			RUN	30 s MEM 321		
			432.1 mbar			Recording stopped
STOP			30 s MEM 901			
Print Record	print quick keystroke: max. output speed  Keystroke approx.1s: single or fast output start/stop printing				PRINT RECORD PUSH PRINT  PRT 432.1 mbar 321 00:13:30  PRT Record stopped	Appears only if values are stored  Printing / display with time  Recording stopped

1) at 70 bar the measurements are stored in [bar]

### 3.4 Configuration

Select mode:

Press  >2 seconds → on the display appears  
CONFIGURATION

Store and exit:

Press  >2 seconds → on the display appears  
SAVE CONFIGURATION

	 MODE SET	 START/STOP PRINT HOLD SELECT	 CLEAR ZERO	Display example	Notes
set unit	<b>mbar, kPa, bar, mmH<sub>2</sub>O, mH<sub>2</sub>O, mmHg, psi, inH<sub>2</sub>O, inHg, hPa, Pa, MPa</b>	2)		UNIT mbar	
set resolution 1)	<b>high</b> low			RESOLUTION high	Display resolution, influences measuring rate in RS 232 mode
set damping	<b>off</b> on			DAMPING off	90% recovery after 4 measurements (when ON)
set baudrate	<b>9600, 4800, 2400, 1200</b>			BAUDRATE 9600	
set auto-off continuous	<b>1, 10, 60 min continue</b>			AUTO OFF 10 min	Automatic switching off or continuous mode
set time unit hours	<b>minutes</b> hours			TIME UNIT minutes	For leak rate, tendency
set Rec. interval 1)	<b>1, 5, 10, 20, 30, 60 s</b> 2, 3, 5, 10, 30, 60 min manual, off			REC INTERVAL 5 s (1.3h)	Off = record mode is deactivated (max. record interval)
set display rate	<b>2.5 Hz (400 ms)</b> 5 Hz (200 ms)			DISPLAY RATE 2.5 Hz (400 ms)	Normal mode indication/zoom (influences DAMPING)
general reset?	set on default values	zero		GENERAL RESET? PUSH ZERO	Reset all settings and clear measurement memory
				GENERAL RESET? RESET OK	After actuating ZERO
print configuration?	print now			PRINT CONFIG? PUSH PRINT	Unit, ...
				PRINT CONFIG? PRINTING	After actuating PRINT

1) If changed, the measurement memory is cleared 2) See in 4.1 "Technical data"

### 3.5 RS 232 mode

The HM28 can be remotely operated from a personal computer via an RS 232 interface. The automatic switching off (chapter 3.1) is inactive. Connection by means of a RS232-cable.

#### Plug pin assignment RS 232, DB 9 (female)

Pin	Assignment	Pin	Assignment
1	DCD	6	DSR
2	TXD	7	RTS
3	RXD	8	CTS
4	DTR	9	SHIELD
5	GND		

#### Protocol

ASCII-commands

9600/4800/2400/1200 baud, 8 bit, no parity,  
1 stop bit,  
XON/XOFF - protocol (17 dec/19 dec)

#### Notes

- The HM28 is switched on when the supply voltage is applied
- The HM28 sends "XON" every 3 seconds To determine the baud rate, read-in "XON" in each transfer rate until "XON" is correctly identified
- To go to remote control mode, interrogate "XON", immediately send the "remote" command and then read-in the acknowledgement "ok"
- Only lower case letters are accepted
- Observe > 0,1 s delay before the next command after "setbaud" command
- To acknowledge the answer of the HM28 without reading it back, just send a "XON"
- The symbol "\*" followed by the checksum must be suffixed to each string. The string must be terminated with a CR
- A "TAB" is prefixed to each answer of the HM28, a "\*" suffixed and the checksum sent.

The answer is terminated with a CR

- The checksum is formed from the least significant byte of the command string

#### Code-decoding of control command «readconfig»

Code	Configuration	Code	Configuration
<b>Pressure unit</b>		<b>Switch. off time</b>	
5	MPa (7-70bar)	0	60 min
6	Pa(25mbar-7bar)	1	continous
7	kPa	2	1 min
8	bar	3	10 min
9	mH2O (with 70bar, otherwise mmH2O)	<b>Time unit</b>	
10	mmHg (not with 70bar)	0	/hours
11	psi	1	/minutes
12	inH2O	<b>Storage interval</b>	
13	inHg (not with 70bar)	2	10 s
14	hPa	3	20 s
15	mbar	4	30 s
		5	60 s
		6	2 min
		7	3 min
		8	5 min
<b>Resolution</b>		9	10 min
0	low	10	30 min
1	high	<b>Damping</b>	
<b>Baudrate</b>		11	60 min
0	1200 Baud	12	manual
1	2400 Baud	13	off
2	4800 Baud	14	1 s
3	9600 Baud	15	5 s
		<b>Display rate</b>	
		0	5 Hz
		1	2.5 Hz

#### Reply to control command «readconfig»

A whole number is returned as a reply

msb    lsb

```
#####
##### #####
||||| | ||| *---- Pressure unit
||||| | |||*----- Resolution
||||| | |||*----- Damping
||||| | |||*----- Baudrate
||||| | *----- Switching off time
||||| *----- Time unit
*----- Storage interval
*----- Display rate
```

Control commands/syntax		Answer from HM28/syntax				Description	
remote	*	182	CR	(tab)[ok]	*	13	CR
local	*	53	CR	(tab)[ok]	*	13	CR
off	*	101	CR	(tab)[ok]	*	13	CR
readpress	*	243	CR	(tab)"Value"	"Unit"	*	Interrogate measurement
readpressfast	*	161	CR	(tab)"Value"	"Unit"	*	Fast measurement interrogation
\$			(tab)[ok]	Checksum	CR (tab)"Value"	*	"RESOLUTION high" output 10 M/s
				*	13		"RESOLUTION low" output 20 M/s
readrange	*	211	CR	(tab)"Range"	"Unit"	*	Checksum
readat	*	253	CR	(tab)"full"/"empty"	230/98	*	Exit "readpressfast" mode
readrecord	*	69	CR	(tab)"Recinterval"	"Value"	-	following send "XON"
			(tab)[record_stopped]	(tab)"Value"	(tab)"Value"	-	CR
			(tab)[out_of_range]	*	*	200	Interrogate measuring range
			(tab)[record_end]	*	*	164	CR
readtemp	*	124	CR	(tab)"Value"	"C	*	Interrogate battery capacity (lobat)
				Checksum		0	(full=ok, empty=change)
							CR
							Interrogate stored measured
clearmem	*	112	CR	(tab)[ok]	*	13	Recording is stopped
readconfig	*	60	CR	(tab)Code (see decoding in table page 17)	*	Checksum	CR
setzero	*	54	CR	(tab)[ok]	*	13	Readout actual configuration
setdefault	*	91	CR	(tab)[ok]	*	13	CR
setunit_kpa	*	146	CR	(tab)[ok]	*	13	Zero indication
setunit_mbar	*	248					Reset all settings and clear memory,
setunit_bar	*	139					change to keypad
							see 4.1 Technical data
							Corresponding units
							see 4.1 Technical data

Control commands/syntax	Answer from HM28/syntax	Description
setunit_mmh2o	*	57
setunit_mmhg	*	255
setunit_psi	*	162
setunit_inh2o	*	54
setunit_inhg	*	252
setunit_hpa	*	143
setunit_pa	*	39
setunit_mpa	*	148
setbaud_9600	*	1 CR (tab)[ok]
setbaud_4800	*	254
setbaud_2400	*	248
setbaud_1200	*	245
resolution_high	*	62 CR (tab)[ok]
resolution_low	*	240
setttempmode_0	*	33 CR (tab)[ok]
setttempmode_1	*	34
setrecipient_off	*	86 CR (tab)[ok]
setrecipient_man	*	87 (tab)[ok]
setrecipient_1	*	76 (tab)[ok]
setrecipient_5	*	80 (tab)[ok]
setrecipient_10	*	124 (tab)[ok]
setrecipient_20	*	125 (tab)[ok]
setrecipient_30	*	126 (tab)[ok]
setrecipient_60	*	129 (tab)[ok]
setrecipient_2m	*	186 (tab)[ok]
setrecipient_3m	*	187 (tab)[ok]
setrecipient_5m	*	189 (tab)[ok]
setrecipient_10m	*	233 (tab)[ok]

Control commands/syntax	Answer from HM28/syntax			
	*	235	CR	(tab)ok
setrecint_30m	*	235	CR	(tab)ok
setrecint_60m	*	238	CR	(tab)ok
setautooff_man	*	198	CR	(tab)ok
setautooff_1	*	187	CR	(tab)ok
setautooff_10	*	235	CR	(tab)ok
setautooff_60	*	240	CR	(tab)ok
setdamp_off	*	115	CR	(tab)ok
setdamp_on	*	21	CR	(tab)ok
setdisrate_2.5	*	23	CR	(tab)ok
setdisrate_5	*	183	CR	(tab)ok
setunit_perh	*	5	CR	(tab)ok
setunit_permiin	*	225	CR	(tab)ok
				(tab)[err]

**Note:** The character – indicates a space

### 3.6 Battery change

- Open battery receptacle
- Insert 9 V-alkali battery (IEC 6LR61) or accumulator

Ensure correct polarity!



Correct disposal of the used batteries according to environment regulations!

### 3.7 Recalibration

**Recalibration to be carried out by specially skilled staff only.**

Relevant instructions see in section 8. We recommend to recalibrate the instrument at least once a year.

## 4 Specifications

### 4.1 Technical data

Measuring media	instrument air or inert gases
Media-compatible types	all media compatible with stainless steel 18/8 (DIN 1.4305)

Units	Measuring ranges			Measuring rate in RS232- mode
	up to 7 bar	10 to 30 bar	70 bar	
mbar	x	x	x	-Class 0,2 20 measurements/s
bar	x	x	x	-Class 0,1 and 0,05 10 measurements/s
Pa	x	-	-	Measuring rate, 2 ½ or
kPa	x	x	x	normal mode 5 measurements/s
hPa	x	x	-	Memory capacity max. 964
MPa	-	x	x	measurements
mmH <sub>2</sub> O	x	x	-	Memory interval manual,
mH <sub>2</sub> O	-	-	x	1,5,10,20,30,60 s
mmHg	x	x	-	2,3,5,10,30,60 min
psi	x	x	x	Display LCD matrix,
inH <sub>2</sub> O	x	x	x	2 lines of 16 characters
inHg	x	x	-	Pneum. ports hose 4/6 mm or
				NPT 1/8"
Linearity, hysteresis and repeatability				Case dimensions 152x83x34/29 mm
(10 °C to 35 °C)	± 0,2 % F.S.			Weight incl. battery 270 g
(50 °F to 95 °F)	(standard) ± 1 digit			
	± 0,1 % F.S.			
	(option) ± 1 digit			
	± 0,05 % F.S.			
	(option) ± 1 digit			
	(according to measuring range)			
Operating temperature	-5 °C to 50 °C (23 °F to 122 °F)			
Storage temperature	-20 °C to 60 °C (-4 °F to 140 °F)			
Humidity	30 to 95 % rH			
Case protection class	IP 54			
Power supply	9 V-battery (IEC 6LR61) or accumulator regulated plug-in mains supply unit (7 to 14 VDC)			
Current consumption	<9 mA			
Operating time (battery)	appr. 70 h			
Baud rate RS232	9600/4800/2400/ 1200 baud			

## 4.2 Measuring ranges

Metric Range	English Range (rounded)	Max. load capacity			Max. static pressure			
0 ... 2.5 kPa	0 ... 10 inH <sub>2</sub> O	12.5	kPa	50	inH <sub>2</sub> O	700	kPa	100 psid
0 ... 7 kPa	0 ... 28 inH <sub>2</sub> O	35	kPa	140	inH <sub>2</sub> O	700	kPa	100 psid
0 ... 20 kPa	0 ... 80 inH <sub>2</sub> O	150	kPa	600	inH <sub>2</sub> O	700	kPa	100 psid
0 ... 30 kPa	0 ... 120 inH <sub>2</sub> O	150	kPa	600	inH <sub>2</sub> O	700	kPa	100 psid
0 ... 50 kPa	0 ... 200 inH <sub>2</sub> O	400	kPa	1600	inH <sub>2</sub> O	700	kPa	100 psid
0 ... 100 kPa	0 ... 14.5 psid/g	400	kPa	58	psid/g	700	kPa	100 psid
0 ... 110 kPa	0 ... 15.9 psia	400	kPa	58	psia	--	--	--
0 ... 200 kPa	0 ... 29 psia/d/g	700	kPa	100	psia/d/g	700	kPa	100 psid
0 ... 700 kPa	0 ... 100 psia/d/g	1700	kPa	245	psia/d/g	1700	kPa	245 psid
0 ... 1000 kPa	0 ... 145 psid/g	2700	kPa	390	psid/g	2700	kPa	390 psid
0 ... 1700 kPa	0 ... 245 psid/g	2700	kPa	390	psid/g	2700	kPa	390 psid
0 ... 3000 kPa	0 ... 435 psig	7000	kPa	1000	psig	--	--	--
0 ... 7000 kPa	0 ... 1000 psig	14000	kPa	2000	psig	--	--	--

a = absolute pressure

d = differential pressure

g = relative pressure

Conversion factors

1 mbar	= 0,1	kPa
1 mbar	= 0,0010	bar
1 mbar	= 10,20	mmH <sub>2</sub> O
1 mbar	= 0,7501	mmHg
1 mbar	= 0,0145	psi
1 mbar	= 0,4015	inH <sub>2</sub> O
1 mbar	= 0,02953	inHg
1 mbar	= 1,0	hPa

☞ The maximum load capacity applies for relative overpressure and negative pressure. **The instrument is calibrated from 0 to 100% of the measuring range.** Exceeding or underrunning this range by up to about 10% is still displayed.

☞ Differential pressure sensors (d) doesn't measure the same value on the P and S side mandatorily because of her geometry.

## 4.3 Power supply unit connection

The HM28 can be operated by a regulated plug-in power supply unit.

Input	115V, 60 Hz
Output	9 V DC ± 20 %, 100 mA (7 to 14 V DC)

## 5 Maintenance

The HM28 requires no maintenance. It can be cleaned with a damp cloth. Do not use cleaning agents containing solvents!

See the relevant chapters for **battery change** and **recalibration**.

## 6 Warning messages and faults

Fault/indication	Possible cause	Remedy
ERROR OUT OF RANGE	10% exceeding or under-running of measuring range	Apply permissible measuring pressure
CHANGE BATTERY	Battery voltage too low	Insert new battery
No change in measurement	Over pressure applied to pressuresensor	Dispatch instrument for repair
Does not switch on	No power supply	Fit new battery as required Battery possibly not correctly inserted Plug in power supply unit correctly
Instrument inaccurate	Inaccurate recalibration	Repeat recalibration
	Not zeroed	Vent and actuate zero
	Natural aging of the pressure sensor	Carry out recalibration

## 7 Accessories

Standard	1 9 V block battery 1 operating instructions
Option	Plug-in power supply unit 115V, 60Hz Leather case with carrying strap Service set Hand pump with variobellows 5bar Handpump 20 bar SCS test certificate Adapter RS232 9M-25F Adapter NPT1/8" Communication SW package comprising: - RS232-IF cable (9 pole fem.) - Communication-software for MS Windows - Measurement places management software for MS Windows

## 8 Calibration instructions

### Recalibration to be carried out by specially skilled staff only!

Actuate the following key combinations:

- First press MODE and keep it pressed
- Next and additionally, press CLEAR/ZERO and keep pressed until CALIBRATION is displayed

Exit from this mode is possible at any time via MODE or OFF.

**The instrument must be in operation for at least 30 minutes** (warm up stabilization time).



New calibration values are only stored when **all five setpoints** have been running through correctly and



**Calibration at 22 °C (71,6 °F) environmental temperature**

Calibration Point	Display	Execute	Notes
	CALIBRATION		
0 % F.S.	CALIB 22 °C SET x mbar	- Set set point x - Press ZERO/CLEAR	0 % F.S. not available with absolute pressure sensor
	OK		
25 % F.S.	SET x mbar	- Set set point x - Press ZERO/CLEAR	
	OK		
50 % F.S.	SET x mbar	- Set set point x - Press ZERO/CLEAR	
	OK		
75 % F.S.	SET x mbar	- Set set point x - Press ZERO/CLEAR	
	OK		
100 % F.S.	SET x mbar	- Set set point x - Press ZERO/CLEAR	
	CALIBRATION OK		

acceptable values acquired. In the event of a maloperation, the calibration process is interrupted and the previous calibration data are retained.

**An incorrect internal instrument temperature can lead to accuracy fluctuations!**

**The pressure set points have to be set in [mbar]!**

**Check the instrument accuracy after recalibration!**



**LOVE CONTROLS Division  
Dwyer Instruments, Inc.  
Highway 212 AT 12  
Michigan City, IN 46360  
USA  
Phone ++1 219 879 8868  
Fax      ++1 219 872 9057**